ANACC Minerals Comy
New Mexico Operations
P.O. Box 638
Grants, New Mexico 87020
Telephone 505 876 2211



June 11, 1982

ALBUQUERQUE DISTRICT MINING

ALE RECEIVED

JUN 14 1982

MINÉRALS MANAGEMENT SERVICE ALBUQUERQUE, NEW MEXICO

Mr. Dale C. Jones District Mining Supervisor Minerals Management Service 500 Gold Avenue, S.W. Room 116 Albuquerque, New Mexico 87102

Dear Mr. Jones:

This is a belated response to the third paragraph of your March 2, 1982 letter to me. I apologize for the oversight.

Attached are three copies of a plan map, 1" = 200, P-10 Final Progress, which shows the location of ventilation fans V.S. 1 and V.S. 2 which are necessary to vent the P-10 decline. These fans are in place and are operative at this time.

Sincerely

R. D. Lynn

General Manager

mls

Attachments

ANACONDA Minerals Company is a Division of AtlanticRichfieldCompany

Albuquerque District Mining Office 500 Gold Avenue SK, Room 116 Albuquerque, New Mexico 87102

March 2, 1982

Hr. Robert D. Lynn General Manager Anaconda Minerals Company New Mexico Operations F. O. Nox 636 Grants, New Mexico 87020

Dear Mr. Lynn:

Thank you for meeting with us to discuss various technicalities in the temporary abandonment of the Jackpile-Paguste Mine, Fueblo of Laguna Uranium Leases 1, 4, and 8.

You have proposed to restrict access to the underground mine workings by placing earthen plugs in all adits and the decline. This procedure is acceptable if you will agree to adequately went the plugs and provide written assurance that Aneconda will reenter and repair these entries as necessary to complete final abandonment procedures. I will notify you when the plugs may be installed.

You have agreed to temporarily cap all ventilation shafts without surface fans by welding vented steel plates over the shaft casings at the collars. The surface fans at all other ventilation shafts will remain in place until you are notified that they may be removed and the shafts temporarily capped. I would appraciate you advising me which two ventilation shafts could be used to ventilate the F-10 decline for final shandonment operations.

During our technical discussion, it was noted that the emergency exit from the P-7 area was blocked at the bottom of the South Paguate Pit by a locked gate. I believe we agreed that this gate should be securely closed by welding, and I would appreciate your assurance that this will be done.

You agreed to investigate the installation of fencing across open-pit access roads to prevent the entry of livestock into the open pits. Please notify we when this effort is completed so that I may inspect the installations for adequacy.

As we agreed, none of the equipment or supplies listed in your February 5 "Jackpile Inventory" will be removed from the leaseholds until the performance bond issue has been resolved.

Thank you again for your cooperation. If you have any questions about the temporary abandonment procedures, please contact me.

Sincerely yours,

(ORIG. SGD.) DALE C. JONES

Dale C. Jones
District Mining Supervisor

cc:

Governor, Pueblo of Laguna
Area Director, Albuquerque Area Office, BIA
Superintendent, Laguna Agency, BIA
Attorney-Advisor Field Solicitor, DOI
Nordhaus, Haltom and Taylor
DMM--Mining, SCR
Mine Plan File: Anaconda Comp. Mine Plan
Chrono, Albuq. District

DCJones:cid 3/2/82 (6827, 6830)